



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	71	Date:	8/26/2004	MeterBasin:	
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	0	Setup No:	3	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
---------------------	-----------------------	---------------------	---------------------

Source Type:	Location:	Severity:
Sector:	Drainage Area: 0	
Comments: No defects observed		

SMOKE TEST PHOTOS

Photo No:

Filename Path:

Image Status: No image name specified.

Photo No:

Filename Path:

Image Status: No image name specified.

Photo No:


Filename Path:

Image Status: No image name specified.

SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 71

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\71.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	71	Date:	8/26/2004	MeterBasin:	
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	0	Setup No:	3	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
---------------------	-----------------------	---------------------	---------------------

Source Type:	Location:	Severity:
Sector:	Drainage Area: 0	
Comments: No defects observed		

SMOKE TEST PHOTOS

Photo No:

Filename Path:

Image Status: No image name specified.

Photo No:

Filename Path:

Image Status: No image name specified.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 71

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\71.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	72	Date:	8/26/2004	MeterBasin:	
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	0	Setup No:	4	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
--------------	----------------	--------------	--------------

Source Type:	Location:	Severity:
Sector:	Drainage Area: 0	
Comments:	No defects observed	

SMOKE TEST PHOTOS

Photo No:
Filename Path:

Image Status: No image name specified.

Photo No:
Filename Path:

Image Status: No image name specified.

Photo No:
Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 72

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\72.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	72	Date:	8/26/2004	MeterBasin:	
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	0	Setup No:	4	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
--------------	----------------	--------------	--------------

Source Type:	Location:	Severity:
Sector:	Drainage Area: 0	
Comments:	No defects observed	

SMOKE TEST PHOTOS

Photo No:
Filename Path:
Image Status: No image name specified.

Photo No:
Filename Path:
Image Status: No image name specified.


Photo No:
Filename Path:
Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

72

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\72.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	73	Date:	8/26/2004	MeterBasin:	01_WR21
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	1	Setup No:	5	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
5812		Ethelbert	AVE

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	25	

Comments:

SMOKE TEST PHOTOS




Photo No: 5

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0826-2004\T-1\PLAYER_A\A_2004_0826Image0005.JPG

Image Status: Image found and displayed.



Photo No: 8

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0826-2004\T-1\PLAYER_A\A_2004_0826Image0008.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

73

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\73.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	73	Date:	8/26/2004	MeterBasin:	01_WR21
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	2	Setup No:	5	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
5820		Ethelbert	AVE

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	0	

Comments:

SMOKE TEST PHOTOS



Photo No: 14

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0826-2004\T-1\PLAYER_A\A_2004_0826Image0014.JPG

Image Status: Image found and displayed.

Photo No: 15

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0826-2004\T-1\PLAYER_A\A_2004_0826Image0015.JPG

Image Status: Can't find image in the specified nam

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

73

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\73.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	73	Date:	8/26/2004	MeterBasin:	01_WR21
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	3	Setup No:	5	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
5814		Ethelbert	AVE

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	0	

Comments:

SMOKE TEST PHOTOS




Photo No: 7

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0826-2004\T-1\PLAYER_A\A_2004_0826Image0007.JPG

Image Status: Image found and displayed.




Photo No: 6

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0826-2004\T-1\PLAYER_A\A_2004_0826Image0006.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

73

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\73.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	73	Date:	8/26/2004	MeterBasin:	01_WR21
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	4	Setup No:	5	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
5810		Ethelbert	AVE

Source Type:	02= Service Line	Location:	5=Sidewalk	Severity:
Sector:	1=Public	Drainage Area:	100	

Comments: hole in ground

SMOKE TEST PHOTOS



Photo No: 16

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0826-2004\T-1\PLAYER_A\A_2004_0826Image0016.JPG

Image Status: Image found and displayed.



Photo No: 17

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0826-2004\T-1\PLAYER_A\A_2004_0826Image0017.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

73

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\73.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	73	Date:	8/26/2004	MeterBasin:	01_WR21
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	1	Setup No:	5	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
5815		Ethelbert	AVE

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	0	

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 6

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0826-2004\T-1\PLAYER_B\B_2004_0826Image0006.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

73

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\73.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	73	Date:	8/26/2004	MeterBasin:	01_WR21
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	2	Setup No:	5	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
3414		Trainor	AVE

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	25	

Comments: hole in ground

SMOKE TEST PHOTOS



Photo No: 7

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\0826-2004\T-1\PLAYER_B\B_2004_0826Image0007.JPG

Image Status: Image found and displayed.



Photo No: 26

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Retakes\UTID73-B2\2005_0523Image026.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

73

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\73.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	73	Date:	8/26/2004	MeterBasin:	01_WR21
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	3	Setup No:	5	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
3400		Trainor	AVE

Source Type:	02= Service Line	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	25	

Comments: hole in ground

SMOKE TEST PHOTOS



Photo No: 8

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0826-2004\T-1\PLAYER_B\B_2004_0826Image0008.JPG

Image Status: Image found and displayed.



Photo No: 25

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\Retakes\UTID73-B3\2005_0523Image025.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

73

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\73.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	73	Date:	8/26/2004	MeterBasin:	01_WR21
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	4	Setup No:	5	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
3400		Trainor	AVE

Source Type:	02= Service Line	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	25	

Comments: hole in ground

SMOKE TEST PHOTOS



Photo No: 9

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0826-2004-T-1\PLAYER_B\B_2004_0826Image0009.JPG

Image Status: Image found and displayed.



Photo No: 25

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\Retakes\UTID73-B3\2005_0523Image025.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

73

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\73.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	74	Date:	8/26/2004	MeterBasin:	01_WR21
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	1	Setup No:	6	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
3414		Rockwood	AVE

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	0	

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 9

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0826-2004\T-1\PLAYER_A\A_2004_0826Image0009.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 74

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\74.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	74	Date:	8/26/2004	MeterBasin:	01_WR21
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	2	Setup No:	6	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
3410		Rockwood	AVE

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	25	

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 10

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0826-2004\T-1\PLAYER_A\A_2004_0826Image0010.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 74

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\74.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	74	Date:	8/26/2004	MeterBasin:	01_WR21
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	3	Setup No:	6	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
3402		Trainor	AVE

Source Type:	04= Cleanout	Location:	9=Yard-Side	Severity:
Sector:	2=Private	Drainage Area:	50	

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 11

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0826-2004\T-1\PLAYER_A\A_2004_0826Image0011.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 74

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\74.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	74	Date:	8/26/2004	MeterBasin:	01_WR21
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	1	Setup No:	6	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
5804		Hamlin	AVE

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	0	

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 10

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0826-2004\T-1\PLAYER_B\B_2004_0826Image0010.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 74

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\74.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	74	Date:	8/26/2004	MeterBasin:	01_WR21
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	2	Setup No:	6	Priority CCTV:	

House Number	3415	Street Prefix:		Street Name:	Rockwood	Street Type:	AVE
Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:			
Sector:	2=Private	Drainage Area:	0				
Comments:							

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 11

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0826-2004\T-1\PLAYER_B\B_2004_0826Image0011.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 74

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\74.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	75	Date:	8/26/2004	MeterBasin:	01_WR19
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	Y
Defect No:	1	Setup No:	7	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:	
5809		Clover	ROAD	
Source Type:	14= Catch Basin	Location:	6=Curb	Severity:
Sector:	1=Public	Drainage Area:	1300	
Comments:	street drainage			

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 12

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0826-2004\T-1\PLAYER_A\A_2004_0826Image0012.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

75

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\75.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	75	Date:	8/26/2004	MeterBasin:	01_WR19
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	2	Setup No:	7	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
5807		Clover	ROAD

Source Type:	04= Cleanout	Location:	9=Yard-Side	Severity:
Sector:	2=Private	Drainage Area:	25	

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 13

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0826-2004\T-1\PLAYER_A\A_2004_0826Image0013.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

75

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\75.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	75	Date:	8/26/2004	MeterBasin:	01_WR19
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	1	Setup No:	7	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
3421		Glen	AVE

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	150	

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 12

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0826-2004\T-1\PLAYER_B\B_2004_0826Image0012.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

75

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\75.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.